

Project No: AFC001-023BCA/BCB

Project: Vandenberg AFB Supplemental RI

Client: AFCEE

Location: Site 2

Borehole ID: HGL-2MW-9

Date: 12/2/99

Geologist: Tom Clifton

SUBSURFACE PROFILE						SAMP	LE	
Depth	Symbol	Description	Elevation	ASTM	Recovery	Moisture	PID (ppm)	Remarks
1-		Sand Hand augered down to 3.0': brown, medium coarse sand with clay and gravel	471.8318	SM				Elevations are from top of casing (ft. above msl)
4-1		Blind Probe Augered down to 4.5'	470.3318					
5		Clay Dark gray clay with sand	468.8318	CL	100%		0.0	Soil sample collected at 5.0 - 5.5' for analysis
8-		Blind Probe Augered down to 9.5'						
10		Clay	465.3318					Cail acrossles called at all at
11		Dark brown to dark gray clay and laminated mudstone with local clasts, stiff	463.8318	CL	100%	damp	555.0	Soil sample collected at 10.0 - 10.5' for analysis
12 13 14 1		Blind Probe Augered down to 14.5'	460.3318					
15 16 17 17		Mudstone Light gray laminated mudstone, stiff, with large dark gray (as above) clay-filled fractures. Contact between mudstone and clay at 14.6', fracture is 0.5" wide	458.8318	CL	100%	damp	47.8/148.0	
18		Blind Probe Augered down to 19.5'						
19		Mudstone	455.3318					
20 - 1		Light gray to white laminated mudstone with local thin vertical fractures filled with dark gray mud as above	453.8318	CL	85%	damp	6.2	
22 - 23 - 24 -		Blind Probe Augered down to 24.5'		,				

Drilled By: West Hazmat

Drill Method: HSA 8"

Drilling Equipment: CME-75

HydroGeoLogic, Inc. 4600 Northgate Blvd., Ste. 207 Sacramento, CA 95834 (916) 614-8770 FAX (916) 614-8775 Hole Size: 8"

Total Depth Drilled: 47'

Sheet: 1 of 2



Project No: AFC001-023BCA/BCB

Project: Vandenberg AFB Supplemental RI

Client: AFCEE

Location: Site 2

Borehole ID: HGL-2MW-9

Date: 12/2/99

Geologist: Tom Clifton

SUBSURFACE PROFILE						SAMPL	E.	
Depth	Symbol	Description	Elevation	ASTM	Recovery	Moisture	PID (ppm)	Remarks
25 26 27		Mudstone Light gray to white laminated mudstone, vertical to subvertical fractures (0.25" wide) filled with dark gray mud as above	448.8318	CL	80%	damp	0.0	
28 -		Blind Probe Augered down to 29.5'	445.3318					
30 31 31		Mudstone Light gray to white laminated mudstone with local iron oxide staining, medium stiff. Fractured chert bed at 30.5'	443.8318	CL	65%	damp	124.0	
32 33 34		Blind Probe Augered down to 34.5'						
35		Mudstone Light gray laminated mudstone with local iron oxide staining along bedding planes	440.3318	CL	80%	dry- damp	113.0	·
37		Blind Probe Augered down to 39.5'						
40 41		Mudstone Light gray laminated mudstone with local dark gray staining along fractures, moist at	435.3318	ML	100%	moist	140.0	Water at 41.0' bgs
42		fractures Blind Probe Augered down to 44.5'					·	
45		Silty Mudstone Grayish brown laminated silty mudstone with	430.3318 428.8318	ML	100%	dry- damp	96.4	
47		abundant iron oxide staining along vertical fractures	427.8318					End of boring 47.0' bgs
48								

Drilled By: West Hazmat

Drill Method: HSA 8"

Drilling Equipment: CME-75

HydroGeoLogic, Inc. 4600 Northgate Blvd., Ste. 207 Sacramento, CA 95834 (916) 614-8770 FAX (916) 614-8775 Hole Size: 8"

Total Depth Drilled: 47'

Sheet: 2 of 2